LIST OF FIGURES

TITLE

PAGE NO

PIGURE NO

| | . The same and the |
|------------|--|
| 1. | A View of Hupari Village as seen from the |
| | Top of the water reservoir in the village |
| 2 | Melting of Silver in a Crucible and The Melted |
| | Silver is poured into a'Pagha (Matric) to |
| | form an ingot. |
| 3. | The Silver rod is passed through the Sut Machine |
| 4. | The Silver rod is passed through the pastha machine |
| 5.+6 | The Silver rodm is passed through the pasta machine |
| | (Strip drawing machine) in order to form astrip of |
| | required gauge. |
| • | The Chain is being soldered with a hand stove |
| 3 | The completed chain is given a slight twist |
| | with the help of a drill machine in order to |
| | get a design. |
| 8 | The 'Spring' is cut into small cieces to get small |
| • | circular rings with opening. |
| 9 0 | The small rings are linkd together to form a chain. |
| | This work is invariably done by females. |
| 10 | The wire is rolled over a steel rod |
| 11 | The Small pieces of design obtained through the press |
| | machine (Photograph No.6) are arranged together and the |
| | the entire orangment is soldered with a hand stove. |
| 12 | Polishing of ornaments by putting them in small |
| | bags of 2.3 Kilograms each. |
| 13 | Polishing of ornaments is done in a Zolana |
| | containing 10 to 15 Kg. ornaments. |
| 14 | Polishing of ornaments with a brush in respect of |
| | some spred ornaments involving intricate designs. |
| 15 16 | Polishing for balls. A few specimen of silver ornaments. |
| •4 | to one allocation on source and an experience of a |