

C O N T E N T S

<u>CHAPTER</u>	<u>TITLE</u>	<u>PAGE</u>
I	<u>FERRITE - AN INTRODUCTION.</u>	
1.1	Introduction.	1
1.2	Historical.	2
1.3	Crystal structure of ferrites.	4
	1.3.a Spinel structure.	4
	1.3.b Garnet structure.	8
	1.3.c Hexagonal structure.	9
1.4	Magnetic properties of ferrite.	11
	1.4.a Magnetisation of ferrites.	13
	1.4.b Anisotropy.	14
1.5	Neel's theory for ferrimagnetism.	17
1.6	Yafet -Kittel Theory.	22
1.7	Spiral structure.	25
1.8	Electrical properties of ferrites.	25
	1.8.a Conductivity.	26
	1.8.b Dielectric properties.	27
1.9	Orientation of problem	29
	References	31

<u>CHAPTERS</u>	<u>TITLE</u>	<u>PAGE</u>
II	<u>PREPARATION OF FERRITE AND X-RAY DIFFRACTION STUDY.</u>	
2.1	Introduction.	33
	Section A - Preparation of ferrite.	
2.2	Preparation of ferrites.	34
2.3	Preparation of ferrite composition.	35
	2.3.a Oxide Method.	35
	2.3.b Decomposition Method.	35
	2.3.c Hydroxide precipitation.	36
	2.3.d Oxalate precipitation.	36
2.4	Presintering.	37
2.5	Sintering.	37
2.6	Sintering atmosphere.	40
2.7	Preparation of ferrite samples .	40
	2.7.a General formula.	40
	2.7.b Method of preparation.	41
	2.7.c Pellet formation.	41
	2.7.d Final sintering.	42

<u>CHAPTERS</u>	<u>TITLE</u>	<u>PAGE</u>
	<u>SECTION B - (X-RAY DIFFRACTION STUDY).</u>	
2.8	Introduction.	42
2.9	Condition for x-ray diffraction.	43
2.10	a) Powder method and its principle.	47
	b) X-ray diffractometer and its principle.	50
2.11	Experimental.	53
2.12	Indexing of the powder pattern.	53
2.13	Results and discussion.	56
	References	71
<u>III</u>	<u>CONDUCTIVITY STUDIES :</u>	
3.1	Introduction.	74
3.2	Conduction mechanism.	76
	3.2.a Conduction in oxides.	77
	3.2.b Mixed valance and controlled Vacancy semiconduction.	78
	3.2.c Conduction in ferrites.	78
3.3	Conductivity.	80

<u>CHAPTER</u>	<u>TITLE</u>	<u>PAGE</u>
3.4	Thermoelectric power.	81
3.5	D.C.conductivity cell and curie temperature determination.	82
3.6	Results and discussion.	87
	References.	110
IV	<u>MAGNETISATION STUDY :</u>	
4.1	Introduction.	113
4.2	Theoretical aspects.	115
4.3	Magnetic Anisotropy.	118
4.4	Irreversibility and Hysteresis.	122
4.5	Losses.	123
	4.5.1 Hysteresis Loss.	125
	4.5.2 Eddy-current loss.	125
	4.5.3 Spin resonance loss	125
	4.5.4 Relaxation loss.	126
	4.5.5 Wall resonance loss.	127
4.6	Experimental.	
	4.6.1 Apparatus.	127
	4.6.2 Measurment procedure.	129

<u>CHAPTER</u>	<u>TITLE</u>	<u>PAGE</u>
4.7	Result and discussion.	130
	References.	147
V	<u>SUMMARY AND CONCLUSIONS.</u>	150
	References.	156