

L I S T O F F I G U R E S

Fig. No.	T I T L E	Page No.
1.1	Spinel Structure of Ferrite	4
1.2	Angle between A-A; B-B, and A-B cations in spinel structure.	8
2.1	Flow Chart for Typical Production Process	22
2.2	X-Ray Diffraction Pattern of Ferrites	
2.2a	CuFe_2O_4	40
2.2b	$\text{Cu}_{0.6}\text{Mn}_{0.4}\text{Fe}_2\text{O}_4$	42
2.2c	$\text{Cu}_{0.4}\text{Mn}_{0.6}\text{Fe}_2\text{O}_4$	44
3.1a	Experimental set up for measurement of conductivity	58
3.1b	Sample holder and Circuit Diagram for Electrical Resistivity and Switching	59
3.2	Plot of $\log \rho$ verses $\frac{1}{T} \times 10^3$	
3.2a	For CuFe_2O_4	63
3.2b	For $\text{Cu}_{0.6}\text{Mn}_{0.4}\text{Fe}_2\text{O}_4$	64
3.2c	For $\text{Cu}_{0.4}\text{Mn}_{0.6}\text{Fe}_2\text{O}_4$	65
4.1.1	Inverse susceptibility of Ferrimagnetic substance as a function of absolute temperature	82
4.1.2	Path of Magnetization about a hysteresis loop	89
4.2	Experimental set up for hysteresis loop measurement	93
4.3a	Actual experimental arrangement to measure Curie temperature	97
4.3b	Experimental set up for Curie temperature measurement	104

FIG. NO.	T I T L E	PAGE NO.
4.4	I - V Characteristics of Copper manganese ferrites quenched from 1000°C	111
4.4a	For CuFe_2O_4	111
4.4b	For $\text{Cu}_{0.8}\text{Mn}_{0.2}\text{Fe}_2\text{O}_4$	112
4.4c	For $\text{Cu}_{0.6}\text{Mn}_{0.4}\text{Fe}_2\text{O}_4$	113
5.1	Scanning electron micrographs of $\text{Cu}_{0.4}\text{Mn}_{0.6}\text{Fe}_2\text{O}_4$ and $\text{Cu}_{0.8}\text{Mn}_{0.2}\text{Fe}_2\text{O}_4$ ferrites.	
5.1a	Sintered at 950°C for 20 hours	142
5.1b	Sintered at 950°C for 30 hours	143
5.1c	Sintered at 950°C for 40 hours	144