

(C O N T E N T)

	Page No.
<u>CHAPTER ONE</u> :	
1.1 Introduction	- 1
1.2 Electrical Neutrality and Types of Compounds	- 3
1.3 Crystal Structure of Ferrites	- 4
1.3a The Inverse Spinel Structure of Ferrite	- 7
1.4 Ceramic Technique	- 11
1.4a Methods of Preparation	- 12
1) Oxide Method	
2) Decomposition Method	
3) Hydroxide Precipitation	
4) Oxalate Precipitation	
1.4b Pre-Sintering	- 13
1.4c Moulding and Extrusion	- 14
1.4d Final Sintering and Cooling	- 15
1.4e Grinding to Shape	- 16
1.5 Conditions of Preparation and Properties of Material	- 16
1.5a Calcination Treatment	- 16
1.5b Repeated Calcinations with Inter-spaced Grinding	- 16
1.5c Sintering Treatment	- 16
1.5d Control of Grain Size	- 18
1.5e Control of Porosity	- 19

...

Table of Content (contd.)

<u>Chapter One (contd.)</u>	Page
1.6 Conductivity in Spinel Ferrites -	20
1.6a Dependence of Resistivity on Excess Iron -	21
1.6b Dependence of Resistivity on the System Composition -	21
1.6c Effect of Impurity on Resistivity -	24
1.6d Effect of Temperature on Resistivity -	24
1.6e Effect of Physical Parameters -	25
1.7 Some Ideas on Conductivity in Ferrites -	25
1.8 Electrical Switching -	27
1.9 Orientation of the Problem -	28
1.10 References -	30
 <u>CHAPTER TWO : SAMPLE PREPARATION AND X-RAY DIFFRACTOMETRY</u>	
2.1 Preparation of Ferrites -	33
2.1A General Formula -	33
2.1B Raw Materials -	33
2.1C Nonstoichiometry -	33
2.1D Mixing of Oxides -	34
2.1E Pre-Sintering -	35
2.1F Milling -	35
2.1G Calcination to Final Product -	35
2.1H Remilling -	35
2.1I Pressing to Shape (Pellets) -	36
2.1J Final Sintering and Quenching of the Pellets. -	36

Table of Content (contd.)

<u>Chapter Two</u> (contd.)		Page
2.2	X-Ray Diffraction Study	- 37
2.2A	Conditions and Directions of Diffraction	- 37
2.2B	X-Ray Diffraction and Structural Analysis	- 41
	i) Laue Method	- 41
	ii) Rotating Crystal Method	- 41
	iii) Principle of the Powder Method	- 42
2.2C	X-Ray Diffractometer and its Principle	- 45
2.2D	Indexing of the Powder Pattern	- 48
2.3	Results and Discussions	- 60
2.4	References	- 63
 <u>CHAPTER THREE</u>		
3.1	Theoretical Development	- 65
3.2	I-V Characteristics Measurements	- 66
3.3	Theories of Switching Behaviour	- 68
3.3a	Voltage Controlled Negative Resistance	- 69
3.3b	Current Controlled Negative Resistance	- 69
3.3c	Bistable Switching or Memory	- 71
3.4	Results and Discussion	- 72
3.4a	Switching in Copper Ferrites $ \text{CuFe}_2\text{O}_4 $	- 76
3.4b	Switching in non-stoichiometric $\text{Cu}_{0.8}\text{Fe}_{2.2}\text{O}_4$ And $\text{Cu}_{0.6}\text{Fe}_{2.4}\text{O}_4$ Ferrites	- 86

...

Table of Content (contd.)

<u>Chapter Three</u> (contd.)		Page
3.4c	Switching in non-Stoichiometric Ferrites of Composition $\text{Cu}_{0.4}\text{Fe}_{2.6}\text{O}_4$ and $\text{Cu}_{0.2}\text{Fe}_{2.8}\text{O}_4$	- 99
3.5	The Theory of Space Charge Limited Currents	- 116 122
3.6	Results and Discussion	- 119 125
3.7	References	- 136
 <u>CHAPTER FOUR</u> :		
4.1	Summary and Conclusion	- 138
4.2	References	- 143

...