

PHOTOGRAPHS



Photo:1 Main wall (48.68 m high &198 m length) and spillway gates of dam.



Photo: 1 Extended water reservoir.



Photo: 3 Jack-well in water reservoir.



Photo: 4&5 Floriculture and banana



Photo: 6&7 Sunflower and Jawar



**Photo: 8&9 Paddy and groundnut
Diversified cropping in the command area of Tulshi dam.**



Photo: 10&11 Pre and post dam impact of irrigation in small valley.



Photo: 12& 13 Undulating structure of topography limits irrigation in valley.



Photo: 14 Water stored in tank being used for irrigation



Photo: 15 Paddy harvesting with manual labours.



Photo: 16 Paddy harvesting with mechanized harvester machine.



Photo: 17 & 18 Jaggery processing and animal husbandry an auxiliary activity of farmers.



Photo: 19 Veterinary services provided to the farmers.



Photo: 20 & 21 Most of the streams in Tulshi basin received perennial source of water.



Photo: 22 & 23 Silt excavation is regular practice in the basin.